


Van National Ltd
 Clarence House
 Clarence road, Longton
 Stoke-On-Trent
 Staffordshire
 ST3 1AZ
 01782 680099
 service@vannational.com
 https://www.vannational.com/

Van National 2022

VHC Date 02/11/2023
 Make VOLKSWAGEN
 Model TRANSPORTER
 Reg No. RV70VDM
 Mileage 45826
 Job Card No. 13765
 Customer Van National
 Telephone 01782680099
 Mobile
 VIN



Number Of Keys	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Key Operation	G		0.00	0.00	No			
Service Intervals And Next Due	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Service Intervals And Due	G	12500 OR 12 months	0.00	0.00	No			
Interim Service - Oil and filter	G		0.00	0.00	No			
Brake Fluid Change	G		0.00	0.00	No			
Full Service - Oil and Air Filter	AM	+ pollen	190.79	190.79	Yes			
Major Service - Oil, Air, Fuel and Pollen Filters	G		0.00	0.00	No			
Timing Belt Replacement/Due	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Replaced/Due	G	133k no time limit	0.00	0.00	No			
Tyres	Status	Report & Recommendations	Depths(mm)			Identified (£)	Authorised (£)	Auth
			Outer	Middle	Inner			
O/S/F Tyre	G	(205, 65, 16 ,)	7.0	7.0	7.0	0.00	0.00	No
N/S/F Tyre	G	(205, 65, 16 ,)	5.0	5.0	5.0	0.00	0.00	No
N/S/R Tyre	AM	Tyre replaced (205, 65, 16 ,)	3.0	3.0	3.0	48.89	48.89	Yes
O/S/R Tyre	AM	Tyre replaced (205, 65, 16 ,)	2.0	2.0	2.0	48.89	48.89	Yes
Spare Tyre	G	(205, 65, 16 ,)	7.0	7.0	7.0	0.00	0.00	No
Body Exterior	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Bonnet Catch/Cable	G		0.00	0.00	No			
Door Locks/Operation	G		0.00	0.00	No			
Exterior Trim/Grille	G		0.00	0.00	No			
Fuel Filler Cover/Flap	G		0.00	0.00	No			
Glass/Windscreen	G		0.00	0.00	No			
Panel Condition	G		0.00	0.00	No			
Number Plates	G		0.00	0.00	No			
Roadwheel Condition	G		0.00	0.00	No			
Slamlocks Operation	G	Not applicable	0.00	0.00	No			
Deadlocks Operation	G	Not applicable	0.00	0.00	No			
Interior	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Carpets	G		0.00	0.00	No			
Door And Roof Seals/Hinges	AM	rear door seal replaced	91.73	91.73	Yes			
Dash Panel Condition/ Interior panels	G		0.00	0.00	No			
Internal Mirrors	AM	internal mirror cover replaced	12.24	12.24	Yes			
Tool Kit/Puncture Kit Date And Location	G	Under passengers seat	0.00	0.00	No			
Locking Wheel/Spare Wheel Nut Location	G	With paperwork	0.00	0.00	No			
Seatbelts	G		0.00	0.00	No			
Time And Date Set Correctly	G		0.00	0.00	No			
12v Socket	G		0.00	0.00	No			
Headlining/Visors	G		0.00	0.00	No			
Door Fitting/Operation	G		0.00	0.00	No			
Load Area	G		0.00	0.00	No			
Door Trim Panels	G		0.00	0.00	No			
Seat Condition And Adjustment	G		0.00	0.00	No			
Steering Wheel/Adjustment	G		0.00	0.00	No			
Electrical Controls	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Horn	G		0.00	0.00	No			

Headlights	G		0.00	0.00	No
Battery Charging Rate	G		0.00	0.00	No
Battery Health Check	G		0.00	0.00	No
Radio/Aerial	G		0.00	0.00	No
Stop Lights	G		0.00	0.00	No
DAB	G		0.00	0.00	No
Rear And Number Plate Lights	G		0.00	0.00	No
Front Fog Lights	G		0.00	0.00	No
Reverse Lights	G		0.00	0.00	No
Rear Fog Lights	G		0.00	0.00	No
Indicator/Hazard Lights	G		0.00	0.00	No
Sidelight/Daytime Running Lights	G		0.00	0.00	No
Beacon/Roof Lights	G	Not applicable	0.00	0.00	No
Interior/Panel Lights	G		0.00	0.00	No
Mirrors Electrical	G		0.00	0.00	No
Wipers/Washers	G		0.00	0.00	No
Air Con Operation And Temperature	G		0.00	0.00	No
Instruments	G		0.00	0.00	No
Starting System/Ignition Lock	G		0.00	0.00	No
Controls/Switches	G		0.00	0.00	No
Sat Nav Operation	G	Not applicable	0.00	0.00	No
Tailift/Tipper Operation	G	Not applicable	0.00	0.00	No
Heater Fan Controls	G		0.00	0.00	No
Window Operation	G		0.00	0.00	No
Reverse camera	G	Not applicable	0.00	0.00	No
Tow bar	G	Not applicable	0.00	0.00	No
Cruise control / Speed limit warning	G		0.00	0.00	No
Stop / start	G		0.00	0.00	No
Parking sensors / Reverse aid	G		0.00	0.00	No
Engine	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth
Engine Oil Level/ Leaks	G		0.00	0.00	No
External Leak Upper Engine	G		0.00	0.00	No
Fuel Pump/Pipes	G		0.00	0.00	No
Engine Mountings	G		0.00	0.00	No
Power Steering Oil Level	G		0.00	0.00	No
Antifreeze Protection/ Level	G		0.00	0.00	No
Radiator/Coolant Cap	G		0.00	0.00	No
Auxiliary Belt	G		0.00	0.00	No
Turbo/Supercharger	G		0.00	0.00	No
Clutch/Brake Fluid	G		0.00	0.00	No
Hoses/Pipes	G		0.00	0.00	No
Front Suspension/Steering/Underframe	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth
Suspension Ball Joints/Track Rod Ends	G		0.00	0.00	No
Subframe/Mountings	G		0.00	0.00	No
Wheel Hub/Bearings	G		0.00	0.00	No
Steering Rack/Box	G		0.00	0.00	No
Suspension Arms/Mountings	G		0.00	0.00	No
Pipes/Hoses	G		0.00	0.00	No
Power Steering Operation/Leaks	G		0.00	0.00	No
Springs/Shock Absorbers	G		0.00	0.00	No
Tie Bars/Anti Roll Bars	G		0.00	0.00	No
Rear Suspension/Underframe	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth
Subframe/Mountings	G		0.00	0.00	No
Springs/Suspension Bars	G		0.00	0.00	No
Suspension Arms/Fixings	G		0.00	0.00	No
Anti Roll Bar/Links	G		0.00	0.00	No
Shock Absorbers	G		0.00	0.00	No
Wheel Hubs/Bearings	G		0.00	0.00	No
Bump Stop/Gaitors	G		0.00	0.00	No
Clutch/Transmission	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth

Mountings	G		0.00	0.00	No
Universal/Sliding Joints	G		0.00	0.00	No
Casings	G		0.00	0.00	No
Drive Shaft Assembly	G		0.00	0.00	No
Gaitors	G		0.00	0.00	No
Fluid/Oil Leaks	G		0.00	0.00	No
Lineage Wear	G		0.00	0.00	No
Manual Fluid Level Check	G		0.00	0.00	No
Hydraulic System	G		0.00	0.00	No
Gear Cables/Operation	G		0.00	0.00	No
Bearings/Supports	G		0.00	0.00	No
Propshaft/Fittings	G		0.00	0.00	No
Flywheel condition	G		0.00	0.00	No
Exhaust System	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth
Joints/Couplings	G		0.00	0.00	No
Pipes And Mountings	G		0.00	0.00	No
Heat Shield/Mountings	G		0.00	0.00	No
Leaks	G		0.00	0.00	No
Catalytic Convertor/Diesel Particulate Filter	G		0.00	0.00	No
Silencer	G		0.00	0.00	No
Manifold	G		0.00	0.00	No
System Condition	G		0.00	0.00	No
Fuel System	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth
Adblue Level/ Condition	G	+10 Ltrs	0.00	0.00	No
Fuel Lines/Filters	G		0.00	0.00	No
Evidence Of Leaks	G		0.00	0.00	No
Pat Fluid Level/ Condition	G	Not applicable	0.00	0.00	No
Tank/ Fixings	G		0.00	0.00	No
Breather Pipes	G		0.00	0.00	No
Brakes	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth
Front Brakes	AM	Pads replaced f discs 27.4	21.60	21.60	Yes
Rear Brakes	AM	Pads replaced r discs 20mm	25.92	25.92	Yes
Handbrake Mechanism	G		0.00	0.00	No
Master Cylinder Security	G		0.00	0.00	No
Handbrake Operation/Adjustment	G		0.00	0.00	No
Pipes/Connections	G		0.00	0.00	No
Servo/Power System	G		0.00	0.00	No
Pedal And Pad/Linkage	G		0.00	0.00	No
Flexible Hoses	G		0.00	0.00	No
Fluid Leaks	G		0.00	0.00	No
Brake Fluid Boiling Point	G	184*c	0.00	0.00	No
Road Test	Status	Report & Recommendations	Identified (£)	Authorised (£)	Auth
Engine Oil Re-Check And Grade	G	6.4l 5w30	0.00	0.00	No
Test Distance	G	9 miles	0.00	0.00	No
Speed Achieved	G	70 mph	0.00	0.00	No
Vehicle Speed Limiter And Set To	G		0.00	0.00	No
Auto Changes/Kick Down	G	Not applicable	0.00	0.00	No
4WD	G	Not applicable	0.00	0.00	No
Road Handling/Stability	G		0.00	0.00	No
Excess Smoke	G		0.00	0.00	No
Suspension Noise	G		0.00	0.00	No
Instrument/Control Function	G		0.00	0.00	No
Handbrake Operation	G		0.00	0.00	No
Wheel Nuts Re-Torqued	G	180nm	0.00	0.00	No
Final Drive Operation	G		0.00	0.00	No
Footbrake Operation	G		0.00	0.00	No
Gearbox Operation/Noise	G		0.00	0.00	No
Engine Performance	G		0.00	0.00	No

Clutch Operation
Warning Lights
Carry Out Diagnostics Check



0.00 0.00 No
0.00 0.00 No
0.00 0.00 No

Technician: Tom Russell
Service Advisor: Rebecca Allcock
Quality Control:

Total Identified (£) Total Authorised (£)
440.05 440.05

Additional Items Details

Additional Items	Mandatory	PartNo	Quantity	Unit Price (£)	VATRate (£)	Price(Inc.Vat) (£)	Auth
	<input type="checkbox"/>		0	0	0	0	<input type="checkbox"/>